RESISTRON



HCB-1

(GB)

Operating Instructions



The current transformer (e.g. PEX-W2, MSW-1) with RESISTRON/CIRUS temperature supplied controllers is used to measure the current of the heatsealing band (secondary current of the impulse transformer) and is an integral part of the control system.

The transformer features a gland approximately 12mm in diameter for the high current wire. In applications with high secondary currents, the required cable crosssection may be larger than the current transformer


The HCB-1 high current busbar represents the ideal solution here. It is adapted to the size of the current transformer gland. M8 bolts for connecting large cable lugs are provided at each end of the busbar.

The information provided in the ROPEX Application Report should be heeded when using the HCB-1 in order to avoid malfunctions.

Installation

The busbar must first of all be inserted through the gland and into the current transformer (Step 1). The high current wire is then fastened using the enclosed

fixing accessories (Step 2). The diagram below shows installation of the busbar on a PEX-W2 current transformer.






Toss Machine Components, Inc. 539 S. Main Street, Nazareth. PA 18064 Phone 610 - 759 - 8883 Fax 610 - 759 - 1766 E-mail info@tossheatseal.com



The high current wire must be connected as follows:



Scope of supply

The HCB-1 high current busbar is supplied with all the required fixing accessories. The scope of supply comprises:

The HCB-1 high current busbar is only allowed to be installed using the enclosed fixing accessories in order to avoid malfunctions.

- 1x busbar
- 2x bolt (M8x25)
- 2x spring lock washer (M8)
- 2x nut (M8)
- 4x washer (M8)

Maintenance

The HCB-1 high current busbar requires no special maintenance. Regular inspection and/or tightening of

the bolts is recommended. Dust deposits can be removed with dry compressed air.

How to order



HCB-1 High current busbar for current transformer Art. No. 885110

Page 2 HCB-1